

Technical Service Bulletin

Attention Service Manager/Parts Department

Bulletin Level: 2* **Specific Warranty Coverage:** Standard warranty coverage

Subject: Solution Leakage

Models Affected:

AquaClean 18FLX, 56265001

Parts List Form Number(s) Affected: 56042452

ECO#: A-04142

Informational Bulletin: N/A

Issue: Solution leaking from under machine

Cause: Barb on Tee fitting 56507993 can be cracked or fractured if fitting is installed using barbs as

a handle or if spray hose is incorrectly oriented.

Corrective Action: Field:

On machines with SN's between 2020917 – 2053323 where leakage occurs replace tee fitting with new nylon tee fitting or replace with adapter fitting 56264382, 90 deg brass street elbow 56396632 & 90 deg brass barb fitting 56470138 as shown in Fig's 2-5.

Factory:

Effective 4/29/08 with SN's noted below the tee fitting material was revised from polyethylene to nylon to increase strength and prevent breakage.

SN's =/> 2053323. Also 2050405, 407-409, 411-416, 418-425, 778-788, 791, 793, 795-802, 1229-1230, 1232-1234, 1236, 1238, 1240-1246, 1248,1251-1255, 1257 & 1259.





Fig 1-

* Technical Service Bulletins Levels:


Level 1: These Bulletins contain general information and are without specific warranty coverage.

Level 2: These Bulletins describe continuous quality improvements that are made to products. Specific warranty coverage may apply and if so is noted in the Bulletin.


Level 3: These Bulletins describe a quality problem that has been determined to require a mandatory update to the product. Specific warranty coverage is as noted in Bulletin.



Note: Effective w/SN 2020917 Items 1, 3 & 5 were replaced with item 8 on the 18FLX







Spray hose orientation if brass fitting used as shown in Fig 2.

Spray hose orientation if plastic T fitting used.




Fig 5-

Fig 4-

Spray hose routed out side of machine and fastened to handle.