

New firmware V 1.24

Machine	TASKI swingo 4000 and 5000
Subassembly	Electronics

Lithium curve and error correction

Within a short time, two versions of the firmware TASKI swingo 4000 and 5000 were released.

To the firmware version V1.23, a new discharge curve for the lithium batteries has been added. This can now be selected in the drop-down menu of the latest version of the TASKI Service Tool.

With the firmware version V1.24, a malfunction in the software, which led to error message E0430 in the case of unfavorable manufacturing tolerances of the brush lowering unit, has now been fixed.

The changes, which were implemented with V1.23, are of course also included in V1.24.

Service Information

- | | |
|--|---|
| <input type="checkbox"/> Check parts on stock | <input type="checkbox"/> Return defective parts to Münchwilen |
| <input type="checkbox"/> Proactive exchange recommended | <input checked="" type="checkbox"/> NO proactive exchange recommended |
| <input checked="" type="checkbox"/> Modification is backwards compatible | <input type="checkbox"/> Modification is NOT backwards compatible |
| <input type="checkbox"/> Update/modify machines in the field | <input type="checkbox"/> Entitled to warranty |
| <input type="checkbox"/> Dispose/recycle defective parts | <input checked="" type="checkbox"/> Parts are available ex stock Münchwilen |
| <input checked="" type="checkbox"/> Others | |

The possibility of building in lithium batteries into our TASKI swingo 4000 and 5000 will be informed officially at a later stage.

Production

TASKI swingo 4000

as of machine number 13062

TASKI swingo 5000

as of machine number 13075