

GTS Newsletter

2012/20E

Machines

Machine	TASKI swift 35, Foam Generator
Subassembly	Valve block

New valve block

We have received feedback that under certain circumstances cracks can develop in the valve block.

The original material was altered in accordance to be RoHs compliant. After testing many samples are we in a position to release the new valve block.

The new valve block has been reinforced with brass insert in the area where the nipples are mounted. The brass inserts are preventing the material from getting cracked.



Description	Material number	Remarks
Valve unit	4117500 (56151-72)	Existing spare part number
Valve unit complete	4130657(56151-87)	New spare part number

Service Information

- | | |
|--|---|
| ☐ Check parts on stock | ☐ Return defective parts to Münchwilen |
| ☐ Proactive exchange recommended | ☒ NO proactive exchange recommended |
| ☒ Modification is backwards compatible | ☐ Modification is NOT backwards compatible |
| ☐ Update/modify machines in the field | ☐ Entitled to warranty |
| ☐ Dispose/recycle defective parts | ☒ Parts are available ex stock Münchwilen |
| ☐ Others | |

Production

TASKI swift 35

as of machine number 3579

TASKI Foam Generator FG

as of machine number 22369