

GTS Newsletter

2009/11E

Machine

Machine	TASKI swingo XP
Subassembly	Electronic

New firmware version 3.32 / optimisation of brush pressure

Under certain circumstances it can occur that the brush pressure on the TASKI swingo XP increases significantly due to an error in the firmware. As a consequence of this error the brush pressure increases until it lifts the machine.

With the update of the firmware to version 3.32 this error can be eliminated.

Service

We recommend updating all machines with the new firmware while doing a service.

⚠ CAUTION

It has to be paid attention that the connection between the machine and the laptop/PC will not be interrupted during the download process. If this happens it could be necessary to exchange the electronics.

Production

TASKI swingo XP

as of machine number 5122