

GTS Newsletter

2023/01E

Machines

Machine	TASKI swingo XP/M-R
Subassembly	Electronics

Optimised electronics

We repeatedly receive feedback from the field, which has shown the E048 on TASKI swingo XP. Several updates have been taken in the past, but not with satisfying results. Internal tests have shown that the error 48 can be triggered amongst others by certain floors and driving behaviors.

In order to reach an optimal result we are reducing the sensitivity of detecting the upper mentioned error. We tested and released an optimised electronics to address this issue on the TASKI swingo XP M-R.

The optimised electronics is backwards compatible with our machines, even in the pre-successor machines.

	
Optimised electronics	Electronics detail with production date

The optimized electronics is recognisable via the production date 38/22, marked with yellow as on photo above. As of production date 38/22 are all optimised electronics.

Description	Material number	Remarks
Electronics	4127085 (18602-43)	Existing spare part number

GTS Newsletter

2023/01E

Service Information

- | | |
|--|---|
| ☐ Check parts on stock | ☐ Return defective parts to Münchwilen |
| ☐ Proactive exchange recommended | ☒ NO proactive exchange recommended |
| ☒ Modification is backwards compatible | ☐ Modification is NOT backwards compatible |
| ☐ Update/modify machines in the field | ☐ Entitled to warranty |
| ☐ Dispose/recycle defective parts | ☒ Parts are available ex stock Münchwilen |
| ☒ Others | |

We recommend replacing electronics to the updated version, which are showing rapidly the error 048.

Production

TASKI swingo XP M-R

as of machine number 5389