

Machines

Machine	TASKI swingo 455E, 755E, 855E, 1255E, Foam Generator
Subassembly	valve, hose, filter

New, improved membrane on the 100-120V magnetic valve

Analyses of returned defective magnetic valve have shown that the membrane can develop fatigue cracks. In order to reduce that, tests with various membrane materials and membrane shapes have been carried out. It turned out that the currently used material offers the best material properties. Due to this learning the focus has been put on the optimization of the shape.



New membrane

Old membrane

Description	Material number	Remarks
Magnetic valve 100-120V complete	4127951 (17609-35)	Existing spare part number

With immediate effect the new membrane is built into the 100-120V version of the valve.

GTS Newsletter

2015 / 24E

Service Information

- | | |
|--|---|
| ☐ Check parts on stock | ☐ Return defective parts to Münchwilen |
| ☐ Proactive exchange recommended | ☒ NO proactive exchange recommended |
| ☒ Modification is backwards compatible | ☐ Modification is NOT backwards compatible |
| ☐ Update/modify machines in the field | ☐ Entitled to warranty |
| ☐ Dispose/recycle defective parts | ☒ Parts are available ex stock Münchwilen |
| ☒ Others | |

We do not recommend a proactive exchange of the magnetic valves in the field.

Production

TASKI swingo 455E 120V
TASKI swingo 755E/855E 120V
TASKI swingo 1255E 120V
TASKI Foam Generator 120V

as of machine number 16312
as of machine number 40901
as of machine number 40901
as of machine number 27560