

Technical Service Bulletin

MODEL(S) AFFECTED: **T1 Floor Scrubber - 230V model only (Part No. 9004195)**
Only models equipped with an analog hour meter.

SUBJECT: Potential electrical discharge issue.
If the machine's power cord is unplugged while the power switch is still in the ON position and the machine is set-up for "double scrub" mode, the user may experience a minor electrical shock if they touch the plug terminals. A small amount of electrical energy is stored within the machine's electrical system resulting in this condition.

PURPOSE: To prevent this condition, the analog hour meter must be replaced with a digital hour meter (order p/n 1047383). The digital hour meter has an internal resistance that dissipates any stored electrical energy.

NOTES: For technical questions or assistance contact:

- Tennant Technical Support Europe.
Email: technical.support.europe@tennantco.com
Phone: +31 413 241 242 the Tennant Customer Service Department.
- Tennant Technical Support Australia and New Zealand.
Phone: +61-2-8718-9722
- Tennant Customer Service North America.
Phone: (800) 553-8033 or (763) 513-2850.

Warranty Information: Standard Terms Apply.



Replace Analog
Hour Meter

Install Digital Hour Meter
(p/n 1047383)

NOTE: Until the analog hour meter is replaced, make sure to instruct the user to turn off the power switch before unplugging the power cord as instructed in the Operator's Manual.