
Attention Service Manager/Parts Department

Bulletin Level: 1* **Specific Warranty Coverage:** Parts: N/A Labor: N/A Travel: N/A

Subject: New Positive Seal/Lock Drain Cap

Models Affected:

- | | | |
|--|---|--|
| <ul style="list-style-type: none"> • 34 RST (all models) • Adgressor (all models) • Adhancer (all models) • Adhancer WB (all models) • Adphibian (all models) • Advenger (all models) • AquaPLUS (all models) | <ul style="list-style-type: none"> • AquaRide (all models) • BA (all models) • BR (all models) • BRX 700 (all models) • Captor (all models) • Condor (all models) • Convertamatic (all models) | <ul style="list-style-type: none"> • ConvertaMAX (all models) • CR (all models) • Haram Captor-CR 1400 • Warrior (all models) • Warrior ST (all models) |
|--|---|--|

Parts List Form Number(s) Affected: 56042380; 56042432; 56042438; 56042439; 56042440; 56042441; 56042446; 56042451; 56042459; 56042463; 56042467; 56042469; 56042470; 56042476; 56042485.

ECO#: A-03912; A-04044; A-04045; A-04046; A-04048

Informational Bulletin: A new recovery tank drain hose is available that has an improved drain hose cap. On some models the new drain hose simply replaces the old hose. Other models require a kit which includes the new drain hose, and a new wider plastic clamp to accommodate the larger diameter of the new drain hose cap assembly.

Issue: The older style drain plugs tended to not seal completely under certain circumstances and could allow some leakage. The new drain cap has a quarter-turn locking feature with an O-ring seal to help prevent leakage from the recovery tank.

Old Style Drain Hose Plug (typical)



Improved Drain Hose Cap (typical)



* **Technical Service Bulletins Levels:**

Level 1: These Bulletins contain general information and are without specific warranty coverage.

Level 2: These Bulletins describe continuous quality improvements that are made to products. Specific warranty coverage may apply and if so is noted in the Bulletin.

Level 3: These Bulletins describe a quality problem that has been determined to require a mandatory update to the product. Specific warranty coverage is as noted in Bulletin.

Part Numbers:

Model	Old Drain Hose Part Number	New Drain Hose Part Number	Notes
Adphibian AquaPLUS AX BA Convertamatic ConvertaMAX	56397142	56601400	Models built prior to serial number 2051347 require kit – p/n 56601412.
Adgressor BR	56314621	56601401	New hose replaces old hose; no kit required.
Adhancer Advenger AquaRide BR BRX	56314487	56691404	New hose replaces old hose; no kit required.
34 RST Adhancer WB BA Warrior	56315638	56601405	Models built prior to serial number 2051347 require kit – p/n 56601413.
Captor CR	56305215	56601406	New hose replaces old hose; no kit required.
	56305624	56601407	
BR Condor	56413151	56601408	New hose replaces old hose; no kit required.

Installation:

- On models that do not require the kit, loosen the worm drive hose clamp, remove the old drain hose, install the new drain hose, then reinstall and tighten the worm drive hose clamp.
- On models that require the kit, you will also need to replace the plastic clamp that holds the drain hose to the machine to accommodate the larger diameter of the new drain hose cap assembly.

Note: A drain hose cap repair kit is also available for the new drain hose that includes a replacement Cap, O-ring, Strap and Strap fasteners. The part number of the repair kit is 56601411.