

GTS Newsletter

2012/07E

Machines

Machine	TASKI swingo XP
Subassembly	Electronic

New firmware version 3.36

We have received feedback that the driving speed between firmware versions varies. Internal tests have shown that minimal differences can be recognised especially when several machines were operated in parallel.

This firmware update is aligning the speed of the different assemblies/versions.

Service Information

- | | |
|--|---|
| ☐ Check parts on stock | ☐ Return defektive parts to Münchwilen |
| ☐ Proactive exchange recommended | ☒ NO proactive exchange recommended |
| ☒ Modification is backwards compatible | ☐ Modification is NOT backwards compatible |
| ☐ Update/modify machines in the field | ☐ Entitled to warranty |
| ☐ Dispose/recycle defective parts | ☐ Parts are available ex stock Münchwilen |
| ☒ Others | |

The firmware adjustment should only be carried out with the current service tool.

⚠ CAUTION

It has to be paid attention that the connection between the machine and the laptop will not be interrupted during the downloading process. In case this happens the electronic must be exchanged.

Production

TASKI swingo XP

as of machine no. 6651