

GTS Newsletter

2011/23E

Machines

| | |
|--------------------|------------------------------------|
| Machine | TASKI swingo 755, 855, 1255 |
| Subassembly | Electronic |

New firmware version 1.11

Internal tests as well as feedback from the field have demonstrated that the basic setting of the start-up speed on the TASKI swingo 755B Power is either faster or sensed as faster as on other TASKI scrubber driers.

This firmware update is adjusting the start-up speed of the TASKI 755/855B Power according to the TASKI machine portfolio. The firmware adjustment does not affect the parameters of the TASKI swingo 1255 machine range.

Service Information

- | | |
|--|---|
| <input type="checkbox"/> Check parts on stock | <input type="checkbox"/> Return defective parts to Münchwilen |
| <input type="checkbox"/> Proactive exchange recommended | <input checked="" type="checkbox"/> NO proactive exchange recommended |
| <input checked="" type="checkbox"/> Modification is backwards compatible | <input type="checkbox"/> Modification is NOT backwards compatible |
| <input type="checkbox"/> Update/modify machines in the field | <input type="checkbox"/> Entitled to warranty |
| <input type="checkbox"/> Dispose/recycle defective parts | <input type="checkbox"/> Parts are available ex stock Münchwilen |
| <input checked="" type="checkbox"/> Others | |

The firmware adjustment should be done with the current service tool 5.0.

⚠ CAUTION

It has to be paid attention that the connection between the machine and the laptop / PC is not getting interrupted during the downloading process. If this happens the electronic has to be exchanged.

Production

| | |
|-------------------------|-------------------------|
| TASKI swingo 755B Power | as of machine no. 15554 |
| TASKI swingo 855B Power | as of machine no. 15554 |
| TASKI swingo 1255 | as of machine no. 15513 |