

GTS Newsletter

2009/06E

Machines

Machine	TASKI swingo XP
Subassembly	Tool

Rubber caps of brushes / pad drive

Feedbacks from the market have shown us that the rubber caps on the pad drives and brushes often get lost. Under certain circumstances this can have a negative impact on the cleaning result.

In collaboration with our supplier a solution could be worked out which is avoiding that the rubber caps fall off. With immediate effect the rubber caps are mounted with stainless countersunk screws. All existing stock in Münchwilen has been refinished.



Description		Remarks
Rubber Cap	4127243 (83004-06)	Material no. remains
Countersunk Screw 3.5x20mm	4128798 (1810/345)	New Material

Service

We recommend to check existing pad drives / brushes when carrying out a service and to adjust them if necessary.

⚠ CAUTION

If you are intending to buy your own screws please ensure to buy 3.5x20mm / stainless / countersunk.