

GTS Newsletter

2008/12E

Machine

Machine	TASKI swingo XP
Subassembly	Chassis

Motordrive/Brake

Feedbacks from the market as well as internal tests have shown us that under some circumstances the swinging arm can squash the motordrive- and the brake cables. This can lead to short circuits and results in damaging the power electronic, the motor drives and/or the brakes.

The cables are now fixed with an additional cable tie above the ball joint (see picture below). The current fixations of the cables to the left and to the right are still necessary.



*New positioning of the cables
(from underneath)*



*Fixation of the cables on the chassis
(from the side of the electronics)*

GTS Newsletter

2008/12E

⚠ CAUTION

Please ensure that the cables are strong tightened to the chassis.

Defective cables must be repaired or replaced in any case.

The brakes are now available as spare parts. We will continue to deliver the motordrives including brakes.

Description	Material number	Status
Brake	4128267 (18603-50)	Available
Motordrive with brake	4126953 (18602-23)	Available
Remarks	-	-

Service

On each TASKI swingo XP service-based visit the motordrive- and brake cables need to be checked on damages and if necessary to be replaced.

The motordrive- and brake cables must be positioned according to the new instruction on all TASKI swingo XP's.

Production

TASKI swingo XP

as of machine number 02626