



GTS NEWSLETTER

TASKI swingo XP

Subassembly: Brush drive

Excentric shaft set 4127427 (18603-10)

Based on field information and internal tests we have faced an increased failure rate of the brush ball bearings caused by humidity. This can result in high vibration or noise from the brush unit.

The corrosion can be decreased with an improved waterproofing.



Content of an excentric shaft set

<u>Art.-No.</u>	<u>Order-No.</u>	<u>Designation</u>	<u>Amount</u>
18600-65	4123937	Excentric shaft (pre-assembled)	1
18603-06	4127398	Cap	1
18600-60	4123704	Bearing bush	1
2538/010	4126644	Bearing 3003 2RS	1
2911/17	4043330	Circlip 17 x 1 A	1
18603-08	4127405	Cover	1
18603-07	4127400	Joint	1
1791/178	4127418	Egalisation washer	1
1723/5	4043560	Self locking nut M6	3

Service

- To modify one machine you need 4 pcs excentric shaft set
- Each excentric shaft set has a documentation (12089-51) in English included
- **Until the end of January 2008** the excentric shaft set is only for **EMERGENCY CASES** available and has to be ordered through GTS

Caution

- Be careful by positioning and pressing the cap into the brush plate

Production

TASKI swingo XP with better splash protected brush unit

from mach.-No. xxxxxx1802