

Attention Service Manager/Parts Department

Bulletin Level: 1*

Specific Warranty Coverage: N/A

Subject: Identification of 24V Cylindrical Brush Motors to Ensure Correct Replacement Parts

Note: This TSB is being reissued due to corrections made to the Models Affected and Brush Motor part number.

Models Affected: 2800D ST and C ST; 3400D ST and C ST; Advenger 2805C-C, 2805D-C, 2805D, 3405D-C, 3405D, X2805C-C, X2805D-C, X2805D and X3405D; AquaPLUS and AquaPLUS AXP; AX 651 Multi EDS; BA 625, 725C, 725 and 825; BR 755C, 755 and 855; Convertamatic 24C-C, 24D-C, 26C-C, 26D-C, 26D, 28C-C, 28D-C, 28D, 32D-C, X24C-C, X24D-C, X26C-C, X26D-C, X28C-C, X28D-C and X32D-C; VacRide 3400 and 3400C

Parts List Form Number(s) Affected: PL56042495, PL56042476, PL56042497, PL56042504, PL56042496, PL56042451, PL56042521.

ECO#: A-04821

Informational Bulletin: Brush Motor p/n 56315061, from an alternate source, was used on production machines for an interim period of time beginning in 2/10. This motor requires the use of alternate replacement parts. Thus, before ordering replacement carbon brushes or brush springs, examine the motor label as shown below to properly identify the motor and order the correct replacement part numbers as listed below the photos.

Standard Motor-Mfg in USA label (Imperial)



Order Replacement Brush/Spring Kit
p/n **56412287**

Alternate sourced motor-Made in China label



Order Replacement Brush/Spring Kit
p/n **56380003**

*** Technical Service Bulletin Levels:**

Level 1: These Bulletins contain general information and are without specific warranty coverage.

Level 2: These Bulletins describe continuous quality improvements that are made to products. Specific warranty coverage may apply and if so is noted in the Bulletin.

Level 3: These Bulletins describe a quality problem that has been determined to require a mandatory update to the product. Specific warranty coverage is as noted in Bulletin.