

Number: TSB-FC-2021-011

Model & Symptom: SC50 fuses supplier and part number

Date: June 4 2021

Author: Christian Rayas

Urgency:

☐

HIGH: Immediate action is required. Service visit must be scheduled.

☐

MEDIUM: Action is required during the next scheduled visit to the machine.

☒

LOW: Action is required if machine is exhibiting the reported issue.

☐

GENERAL: No action is required

SYMPTOM:

SC50 uses fuses in the electrical system. Currently, there are no Nilfisk part number for these fuses:

Fuse name	Motor	Supplier	Part number	Amps
F3	Vac motor	Littelfuse	287030	30A
F4	Scrub motor	Littelfuse	287040	40A
F5	Actuator	Littelfuse	287015	15A
F6	Drive motor	Littelfuse	895040	40A slow-blow
F7	UVGI	Littelfuse	287020	20A

PRODUCTS:

- All SC50 models: 56104502, 56104503, 56104506, 56104507, 56104508, 56104509, 56394519, 561394521, 56394600, and 56394601.

SYSTEM:

Electrical system, UVGI system.

RELATED TFR / PRIOR TSB:

None.

ISSUE:

No Nilfisk part number on these fuses makes difficult to know have stock, and to communicate to field technicians supplier and part number.

CAUSE:

Missing documentation.



Number: TSB-FC-2021-011

Model & Symptom: SC50 fuses supplier and part number

Date: June 4 2021

Author: Christian Rayas

Urgency:

☐

HIGH: Immediate action is required. Service visit must be scheduled.

☐

MEDIUM: Action is required during the next scheduled visit to the machine.

☒

LOW: Action is required if machine is exhibiting the reported issue.

☐

GENERAL: No action is required

PRODUCTION CORRECTIVE ACTION

ECR 11296 created to request the creation of Nilfisk part numbers for the fuses mentioned before.

PRODUCTION SOLUTION IMPLEMENTATION DATE and / or SERIAL NUMBER:

Machine serial break not applicable.

ECO in process.

FIELD CORRECTIVE ACTIONS

In case you need to replace a fuse in the SC50, refer to the fuse list on this TSB for manufacturer and manufacturer part number.

SPAREPARTS and/or SERVICE KITS

To be created.

ECO / ODM / ECN #:

In process.