

Technical Service Bulletin

TSB-IT 2012-093
Floor Cleaning Equipment

Subject: New hoses squeegee vacuum

5 October 2012

Ref. ODM Nr: 4777

Models Affected	BA 451/531 - SCRUBTEC 5xx BA 551/611 - SCRUBTEC 6xx BA 651/751/851
Issue	Premature damage of the squeegee vacuum hose.
Corrective Action: Factory	Supplier change from PVC to blended PU-PVC to allow higher chemical resistance and new spiral shape for higher flexibility. New hoses implemented in production as running change, starting Serial Nr. 3510123804553 / Sept. 2012.
Corrective Action: Field	Interchangeability guarantee.
Spare Parts	GREY squeegee vacuum hose PN 909 6230 000 replaced by new 9099852000 (KIT 9097619000 include new 9099852000 as running change) BLACK squeegee vacuum hose PN 9097069000 replaced by new 9099853000

OLD



NEW

From: Alberto Rastelli

Email: floorcare-techsupport.it@nilfisk-advance.com

Page 1 of 1

Level of Urgency:

- 1: „High“ - Rework needs to be done immediately
- 2: „Medium“ - Rework to be made at next possible occasion
- 3: „Low“ - Rework to be done if necessary
- 4: „General“ - General information

4