

TECHNICAL SERVICE BULLETIN



Nilfisk

Number: TSB-FC-2015-049

Symptom: New hour counter option

Date: 5th Feb 2016

Urgency: Low

Author: Alberto Rastelli

Urgency:



HIGH: Rework needs to be done immediately



MEDIUM: Rework needs to be done by next possible occasion



LOW: Rework to be done if necessary



GENERAL: General information

Informational bulletin:

New hour counter OPTION

ODM: 5873

PRODUCTS:

Nilfisk SC450 B

ALTO SCRUBTEC 453 B

SYSTEM:

Electrical system

SPARE PARTS or Kits Needed:

P/N 9096951000 - COUNTER HOUR 24V KIT (include hour meter assy and instructions)

It is possible to retrofit the hour counter on machines before the breaking SN **3510152409826** by:

P/N 9100000949 - COUNTER HOUR 24V ADAPTOR KIT (include hour meter assy, new decals, adaptor wires and instructions)

