

Brush Motor Replacement Kit

7



Models: T7 Cylindrical / Speed Scrub Rider Cylindrical

This motor replacement kit is intended for machines manufactured before serial number 10405584. Brush motor p/n 604980 has been discontinued and replaced by this kit which includes additional parts for proper installation. Carefully follow the installation instructions below.

INSTALLATION INSTRUCTIONS:



MARNING: Electrical Hazard. Disconnect Battery Cables Before Servicing Machine.

