

TECHNICAL SERVICE BULLETIN



Nilfisk

Number: TSB-FC-2016-012
Symptom: Informational bulletin
Date: 25th July 2016
Urgency: Low
Author: Alberto Rastelli

Urgency:



HIGH: Rework needs to be done immediately



MEDIUM: Rework needs to be done by next possible occasion



LOW: Rework to be done if necessary



GENERAL: General information

Informational bulletin:

Pad holder thickness reduced (-10mm) and aligned to the same height of the brush.

PRODUCTS:

SC400 all, SCRUBTEC 343.2, Vantage 17

SYSTEM:

Brush system

Change Notice - 1005380

SPARE PARTS or Kits Needed:

Old P/N 909 5695 000 - PAD HOLDER KIT closed, replaced by

New P/N 9100001897 - PAD HOLDER BRISTLE 17 430MM

Old P/N 9099669000 - PAD HOLDER FLAT 17 432MM closed , replaced by

New P/N 9100002050 - PAD HOLDER FLAT 17 432MM

COMPONENT LOCATIONS / PICTURES:



**PAD HOLDER
BRISTLE**

Thichenss reduced



PAD HOLDER FLAT

Thichenss & diameter
reduced