

TSS Bulletin

Date 06-21-2012, Issue 29


Purpose: Swingo 350B Recovery Tank Drain Plug Upgrade

In some cases the drain plug has separated from the tank and affects recovery pickup performance. This update to the drain plug assembly will prevent this from happening.

Step 1: Remove the screw from the drain plug using a Torx T-30. Set screw aside as you will reuse it.



Step 2: Add the washer (part # 192-0248) to the drain plug.



Step 3: Replace the screw using the Torx T-30.

