

DATE OF BULLETIN:

9-07-2017

THIS BULLETIN SUPERSEDED BULLETIN(S):

None.

MODELS AFFECTED:

SPORT	PRO
CARBON	XR
HERO	

MACHINE SYMPTOMS:

None.

SCOPE OF BULLETIN:

Cylindrical hoppers removable from either side (left or right).


Cylindrical models now have a crows foot tool standard for easy access and repairs to motors.

MATERIALS REQUIRED:

None.

REVISIONS:

All Cylindrical hoppers (minus GTX) will be revised to accommodate removal from the right or left side. This change should be complete on all machines by Jan. 1st, 2018. These hoppers are completely interchangeable with old hoppers and decks.



Right Hand Side Hopper Removal



Left Hand Side Hopper Removal



Cylindrical models now have a crows foot tool standard for easy access and repairs to motors.

Crows Feet Tool



Crows Feet With Socket Driver



Crows Feet Storage Location



Crows Feet Socket Driver In Use

