



**DATE OF BULLETIN:**

1-29-2014

**THIS BULLETIN SUPERSEDED BULLETIN(S):**

None

**MODELS AFFECTED:**

*Tomcat Floor Sweepers*

**MACHINE SYMPTOMS:**

Uneven traction and wheels out of round.

**SCOPE OF BULLETIN:**

To inform about the new models of Floor Sweepers as well as the new standard tires and new standard Control sticker for Walk Behind Sweeper Machines that begin on February 1<sup>st</sup>, 2014.

**MATERIALS REQUIRED:**

To update old machine tires to current specifications use the part numbers listed below.

**TOMCAT GT:** Part # 4-618595 - \$48.28

**REVISIONS:**

- **TOMCAT GT** - GT Sticker Part #: 4- 2006 (No Charge To Upgrade Machine)

PCB-629



- **TOMCAT VR** - VR Sticker Part #: 349- 2006 (No Charge To Upgrade Machine)




- **TOMCAT GT Wheels** - 10" (25.4cm) × 2.5" (6.35cm)



You will notice that in the 2014 Updated Pricing the Heavy Duty Package has gone away as there is only one size wheel now. Now only the HD Bumper needs to be added when purchasing.

- **Control Sticker**



New sticker shows where certain control options will be to better aid in operation:

**Power Switch:** Downward Position - OFF, Middle Position - Main Broom Only, Top Position - Main Broom and Side Broom.

**Key Switch:** Optional area for if customer wants a Key Switch to prevent unauthorized machine usage.

**Recharge Counter:** Displays total amount of recharge cycles.

**Side Broom Speed Control:** Optional Area if customer wants the ability to speed up and slow down Side Broom.