


Machines

Machine	TASKI swingo XP
Subassembly	Electronic

USB Cable

For a more comfortable data exchange a new USB cable will be integrated into the machine. The cable is connected to the data interface of the electronic.



Description	Order number	Remark
USB Cable 3m	4129688 (18603-93)	New Spare Part Number

Service

We recommend updating existing machines with the new USB cable if required.

The interface cable can't be made accessible from outside ex factory. This would require a new certification of the machine.

⚠ CAUTION

By making the interface cable accessible from outside it has to be paid attention where to position it (mechanical damage as well as splash water protection)!

Production

TASKI swingo XP

as of machine number 5764