





# GTS NEWSLETTER

## TASKI ergodisc 165/200/300/400/Duo Subassembly: Drive

*Replaces GTS Newsletter N2004/04*

### Brush housing

The actual mounted brush housing will be replaced by a new, strengthened brush housing which has an integrated, stuck bumper profile (see drawing LH).



### Service

- All ergodisc models (Ø 43 cm) can be retrofitted with the new brush housing
- With immediate effect, only new brush housings are delivered
- The covering profile and the supporting clamp set are still available

	Old	New
<b>Brush housing</b>	4122576 (14604-33)	replaced by 4126760 (14604-46)
<b>Bumper profile</b>	4118090 (14600-97)	not anymore available
<b>Covering profile</b>	4116970 (8662/008)	still available
<b>Supporting clamp set</b>	4117460 (14604-19)	still available

### Caution

For ergodisc models Ø=38 cm and Ø=50 cm, a separate GTS Newsletter will follow.

### Production

TASKI ergodisc with new brush housing

from machine-No. xxxxxxxx54624