



PCB-640

DATE OF BULLETIN:

6-28-2017

THIS BULLETIN SUPERSEDED BULLETIN(S):

None

MODELS AFFECTED:

SPORT

MACHINE SYMPTOMS:

None

SCOPE OF BULLETIN:

Increased tank dimensions and capacity for the standard tanks.

MATERIALS REQUIRED:

Old machines with 10g Sol./10g Rec. tanks cannot be equipped with new 13g Sol./15g Rec. tanks.

SPORT 10g Sol./10g Rec. Tank Kit #: 155-4140W


SPORT 13 Sol./15 Rec. Tank Kit #: 155-4142W

REVISIONS:

Increased tank dimensions and capacity for the standard tanks to more easily qualify which machine an End-user should purchase and bring popular features from larger CARBON/HERO down to the smaller SPORT.




Tank Line Profile





Bandeau & Suds Reservoir:

Added Vacuum Bandeau System (identical to the CARBON/HERO) to the tanks to protect the Vacuum Motor as well as reduce dB levels of the machine. Bandeau System includes blue drain hose (Image A) for moisture that potentially gets past the vacuum motor. New added space for Suds reservoir (Image B). Green Hose (Image A) included on all SPORTS for Suds reservoir draining.



Baffle Assembly:

Added enlarged Drain Saver Basket like the CARBON/HERO. Yellow drain saver baskets will be standard after August 1st.



Central Command:

New Central Command like CARBON/HERO to allow for more components and options. This new style can be equipped to 10g Sol./ 10g Rec. tanks.

