

Machines

Machine	TASKI swingo scrubber driers
Subassembly	Squeegee

New ceramic axle of the supporting wheel

We repeatedly received feedback and samples of heavily abraded axles. The abrasion of the axles can have a negative impact on the suction result of the machine, as angle and/or the distance from the squeegee to the floor changed.

To increase the durability of the axles and keep the good suction result, new axles made out of ceramic have been introduced.



Supporting wheel with ceramic axle



ceramic axle

Description	Material number	Remarks
Ceramic axle	4127883 (18603-30)	Existing spare part number

Service Information

- | | |
|--|---|
| ☐ Check parts on stock | ☐ Return defective parts to Münchwilen |
| ☐ Proactive exchange recommended | ☒ NO proactive exchange recommended |
| ☒ Modification is backwards compatible | ☐ Modification is NOT backwards compatible |
| ☐ Update/modify machines in the field | ☐ Entitled to warranty |
| ☐ Dispose/recycle defective parts | ☒ Parts are available ex stock Münchwilen |
| ☒ Others | |

The spare parts stock in Münchwilen has already been replaced.

Production

The ceramic axle will be introduced to the complete machine range.